

Update on C Support Files and Locations

As of March 31st, I moved the location of the C support files on the **Y:** drive. The old location was:

Y:\MWorks and Y:\MWorks\WWU

The new location is:

Y:\emicros\ProjS12

This was done, not only because MetroWerks no longer exists but also to make the folder organization scalable when adding new MCUs.

In addition, the naming convention for the CodeWarrior program directory was changed to a more generic location so the support files do not have to change every time I upgrade CodeWarrior. The new location is:

C:/Program Files/Freescale/Codewarrior for HC12/

This impacts the **Makefile** and the **project.ini** environment file.

As a result of these changes, I have changed the **Makefile**, **project.ini**, and two files in **OSProj** for MicroC/OS projects. This means your projects from ETec454 and your senior project code, if started, will have to change in order to work with the new rebuild.

Here are the detailed changes:

Makefile. The lines:

```
MWPROG = "C:/Program Files/Metrowerks/Codewarrior CW12_V3.1/Prog/"  
#MWPROG = "Y:/Mwerks/CW12_V3.1/Prog/"
```

were replaced with:

```
CWPROG = "C:/Program Files/Freescale/Codewarrior for HC12/Prog/"
```

Then all instances of **MWPROG** were replaced with **CWPROG**.

project.ini. All instances of **MWorks** or **MWorks/WWU** were replaced with **emicros/ProjS12**

OSProj/ucos12. All instances of **MWorks** or **MWorks/WWU** were replaced with **emicros/ProjS12**

OSProj/ucos-ii. All instances of **MWorks** or **MWorks/WWU** were replaced with **emicros/ProjS12**

I believe that is it. If you find any errors, instances of the **MWorks** path, or other issues that cause problems, please let me know.